	Application No.	Applicant(s)
	09/930,572	PINKHAM, LOUIS V.
Notice of Allowability .	Examiner	Art Unit
	John Rivell	3753
The MAILING DATE of this communication apper All claims being allowable, PROSECUTION ON THE MERITS IS herewith (or previously mailed), a Notice of Allowance (PTOL-85) NOTICE OF ALLOWABILITY IS NOT A GRANT OF PATENT RI of the Office or upon petition by the applicant. See 37 CFR 1.313	(OR REMAINS) CLOSED or other appropriate comr GHTS. This application is	in this application. If not included nunication will be mailed in due course. THIS
1. This communication is responsive to <u>amendment filed 10/2</u>	9/04 and oath/amendmen	<u>t filed 12/2/05</u> .
2. The allowed claim(s) is/are <u>1-20</u> .		
3. \boxtimes The drawings filed on <u>01 May 2002</u> are accepted by the Ex	aminer.	
 4. Acknowledgment is made of a claim for foreign priority una a) All b) Some* c) None of the: 1. Certified copies of the priority documents have 2. Certified copies of the priority documents have 3. Copies of the certified copies of the priority documents have International Bureau (PCT Rule 17.2(a)). * Certified copies not received: 	been received. been received in Applicat	ion No
Applicant has THREE MONTHS FROM THE "MAILING DATE" on noted below. Failure to timely comply will result in ABANDONM THIS THREE-MONTH PERIOD IS NOT EXTENDABLE.		le a reply complying with the requirements
5. A SUBSTITUTE OATH OR DECLARATION must be submit INFORMAL PATENT APPLICATION (PTO-152) which give		
 CORRECTED DRAWINGS (as "replacement sheets") muse (a) including changes required by the Notice of Draftspers hereto or 2) to Paper No./Mail Date including changes required by the attached Examiner's Paper No./Mail Date Identifying indicia such as the application number (see 37 CFR 1. 	on's Patent Drawing Revies s Amendment / Comment	or in the Office action of
each sheet. Replacement sheet(s) should be labeled as such in the	-	• •
7. DEPOSIT OF and/or INFORMATION about the deposit attached Examiner's comment regarding REQUIREMENT I		
 Attachment(s) 1. ☐ Notice of References Cited (PTO-892) 2. ☐ Notice of Draftperson's Patent Drawing Review (PTO-948) 3. ☑ Information Disclosure Statements (PTO-1449 or PTO/SB/0 Paper No./Mail Date 05012009 (correct) 4. ☐ Examiner's Comment Regarding Requirement for Deposit of Biological Material 	6. ⊠ Interview Paper No 8), 7. ⊠ Examiner	Informal Patent Application (PTO-152) Summary (PTO-413), b./Mail Date <u>11142005</u> s Amendment/Comment s Statement of Reasons for Allowance

Art Unit: 3753

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

The application has been amended as follows in order to correct the procedural deficiencies in the amendment to the specification filed October 29, 2004 and in the supplemental amendment to the claims filed December 2, 2005. Specifically, the use of double bracketing and strikethrough for the deletion of subject matter in the specification and the use of double bracketing for the deletion of subject matter from the claims does not conform to 37 CFR 1.173(d). In addition, during the interview of November 14, 2005 with Mr. Won Joon Kouh, the below amendment to the claims was discussed and agreed to. The supplemental oath filed December 2, 2005, required by the Examiner during the interview, is intended to cover all amendments below.

IN THE SPECIFICATION:

Please amend the last paragraph ending at line 50 of column 1 as follows:

Fluid can flow through the prior art valve assembly 10 depicted in FIG. 1A in any one of the three directions depicted in FIGS. 1B-1D. The fluid flow is represented by arrows 25 in these figures. In FIG. 1B, which represents the forward product flow through the column, valve 14a is opened allowing the fluid to flow from the process piping into the valve assembly 10. Valve 16a is also opened allowing the fluid to flow into the chromatography column (not shown). The fluid returns from the chromatography column passing through valve 16b and reentering the valve assembly.

Art Unit: 3753

3A;

The fluid leaves the valve assembly passing through valve 14b on its path back to the process piping. Valves 12a and 12b remain closed during this process. According to the reverse process flow depicted in FIG. 1C, fluid entering the valve assembly 10 from the process piping can flow through valves 12a and 16b into the column, returning from the column through valve 16a, and exiting the valve assembly through valve [12a] 12b back through the process piping. Valves 14a and 14b remain closed during this process. The column may be bypassed altogether according to the process flow depicted in FIG. 1D, where the liquid entering into the valve assembly from the process piping encounters opened valves 12a, 14a, 12b and 14b, exiting the valve assembly without entering the chromatography column which remains inaccessible by closing valves 16a and 16b.

Please amend the fifth full paragraph of column 3 starting at line 24 as follows: FIG. 3B is an enlarged cross-sectional view through line [A—A] 3B-3B of FIG.

Please amend the last paragraph of column 3 starting at line 36 as follows:

Referring to FIG. 2, there is shown a perspective view of the instant invention chromatography valve assembly 30. The valve assembly 30 comprises a unitarily formed valve body 32, which may be cast or machined from iron, bronze, stainless steel or aluminum, or may be molded from a suitable plastic or plastic composite material. The outer body 32 is generally that of an octahedral pyramid having a octagonal base 34, a square top surface 36, and a combination of triangular 35 and distorted hexagonal 48 side faces. The top square surface 36 is planar and mounted thereon is the first of

Art Unit: 3753

five manual bonnet assemblies 38,39,40,41,42 for manually controlling the operation of the underlying valves. The operation of manual bonnets in diverter valve assemblies is well known to those skilled in the art, and is explained, for example, in afore-described U.S. Pat. No. 5,273,075, the specification of which is incorporated herein by reference. It should be noted that although manual bonnet assemblies are shown, other means such as pneumatic or electrical actuators may be mounted on the outer valve body in order to control the valves, thereby eliminating the need for the manual bonnets. The manual bonnets as shown are affixed to the valve body via plates 44, each plate having four suitable screw-type fasteners 46. Extending downwardly and outwardly from each edge of the top square surface 36 of the valve body 32 is a distorted hexagonal side face 48, each side face being planar and having a manual bonnet mounted thereon. These side faces are angled at approximately [22° (specifically 22.21°)] 30° with respect to the octagonal base of the valve body. The reason for the particular angled mounting of the additional four bonnet assemblies 39,40,41,42 has to do with valve drainage concerns, and will also be explained in detail later.

Please amend the paragraph starting at column 4, line 9 as follows:

Referring now to FIG. 3A, there is shown a top view of the valve assembly, minus the manual bonnets and with a partial cross-sectional view of the underlying channel network drawn in with broken lines. As can be seen in this figure, ports 50, 52, 54 and 56 are arranged at angles of approximately 90° with respect to each other on opposing ends of the octagonal base section of the valve assembly. Each port opens into a chamber in the valve assembly 30--port 50 opening into chamber 60, port 52 opening

into chamber 62, port 54 opening into chamber 64, and port 56 opening into chamber 66. Fluid entering any of the ports encounters a chamber and channels leading to <u>up to</u> three diverter valves. <u>Fluid entering port 52, for example, encounters chamber 62 and channels leading to two diverter valves 70 and 72. Where as fluid [Fluid] entering port 50, for example, encounters chamber 60 and channels leading to diverter valves 70, 76 and 78. The smooth and tortuous network of passageways that lead through the valve assembly connect the ports with the chambers and valves in a such a way that the valve assembly is fully drainable as will be later explained. The flow of the fluid is controlled by the diverter valves 70,72,74,76,78 and may be adjusted to permit specific flow directions which, in combination with the smooth and tortuous passageways, eliminate dead-legs from the system.</u>

Please amend the third paragraph of column 4 starting at line 31 as follows:

Referring now to FIG. 3B, there is shown an enlarged cross-sectional view of the valve assembly through line [A—A] <u>3B-3B</u> of FIG. 3A. As can be seen in the figure, port 50 opens into chamber 60. A passageway 55 leading to diverter valve 76 can also be seen in this figure. Chamber 60 is connected to chamber 64 via diverter valve 78. The passageway that connects these two chambers is inclined, rising sharply before encountering diverter valve 78 and then falling sharply after encountering the valve. The angle of inclination 63 measured from either side of the diverter valve 78 is approximately 30°. In chamber 64, a passageway 65 leading to diverter valve 74 can be seen. Finally in this figure, port 54 can be seen as opening into chamber 64.

Please amend the fourth paragraph of column 4 starting at line 44 as follows:

Referring now to FIG. 3C, there is shown an enlarged side elevational view of the instant invention valve assembly 30. This particular side elevational view is directed down port 50 which is disposed on triangular surface 35. As explained above, port 50 opens into chamber 60 which is connected by channels to diverter valves 70, 76 and 78. In this figure, diverter valves 70 and 76 can be seen on opposite sides of port 50, being disposed beneath the afore-described distorted hexagonal side faces 48. These diverter valves, as well as diverter valves 72 and 74 (not shown in this figure), are machined in the position of their drain angle which is approximately [22° (specifically 22.21°)] 30° as measured from the octagonal base of the valve assembly. This arrangement, coupled with the fact that valve 78 (as seen in FIG. 3B) is at a high point in the valve assembly, allows the valve assembly 30 to be fully and easily drainable. Ports 56 and 52 are also clearly visible in this figure.

IN THE CLAIMS:

2 (amended). The diverter valve assembly of claim 1, wherein said valve body comprises an octahedral pyramid structure having:

a substantially planar, octagonally shaped base portion;

a substantially planar square top surface;

four distorted hexagonal side faces projecting downwardly [form] <u>from</u> said square top surface; and

four triangular faces rising perpendicularly from said base portion, said triangular faces being disposed between said four side faces.

7 (amended). The diverter valve assembly of claim 6, wherein one of said five diverter valves is disposed at a predetermined high point in said valve body and the other four of said five diverter valves are disposed in said valve body at predetermined angles suitable for draining said valve assembly.

8 (amended). The diverter valve assembly of claim 7, wherein said angles are approximately [22°] 30°.

11 (amended). A diverter valve assembly for use in a liquid chromatography system, comprising:

a unitarily formed valve body having a plurality of chambers and a tortuous network of passageways extending therethrough;

at least one inlet port connected to one of said plurality of chambers for receiving the flow of a liquid into said [valves] valve assembly;

at least one outlet port connected to one other of said plurality of chambers for allowing said liquid to exit said valve assembly;

at least two additional ports connected to two other of said plurality of chambers for allowing the flow of liquid already in said valve assembly to exit and reenter said valve assembly without exiting into said chromatography system; and

a plurality of diverter valves interposed between said plurality of chambers and ports, wherein fluid entering [any one] up to two of said ports encounters one of said chambers and sections of three of said channels which lead to three of said diverter valves thereby permitting a complete flushing of said valve assembly.

13 (amended). <u>A unitarily formed</u> [The] diverter valve assembly for diverting the flow of fluids in a liquid chromatography system comprising:

first, second, third, and fourth ports;

first, second, third and fourth chambers; and

first, second, third, fourth and fifth diverter valves;

wherein said first port is associated with said first chamber, said second port is associated with said second chamber, said third port is associated with said third chamber, and said fourth port is associated with said fourth chamber; and

wherein said first diverter valve is disposed between said first and said second chamber, said second diverter valve is disposed between said second and said third chamber, said third diverter valve is disposed between said third and said fourth chamber, said fourth diverter valve is disposed between said fourth and said first chamber, and said fifth diverter valve is disposed between said first and said third chamber.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to John Rivell whose telephone number is (571) 272-4918. The examiner can normally be reached on Mon.-Thur. from 6:30am-5:00pm.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Stephen Blau can be reached on (571) 272-4406. The fax phone number for the organization where this application or proceeding is assigned is 571-273-8300.

Application/Control Number: 09/930,572

Art Unit: 3753

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

/ John Rivell
Primary Examiner
Art Unit 3753

Page 9